



Caution: (1) This Diagram is designed ONLY for the Non-USA AND Non-Canadian Models of the Yamaha 1700 V-Max.
 (2) Installation is at Installer's Risk

- Soldered Tapped Connection
- Soldered Wire Connection

Color (Added Wire) - Color of Wire is Installer's Choice

**CMS Pro Meter Kit Installation Diagram
 (with Break-Out Box Type-A)**
 19 Dec 2012 v1.3_N